EA 98-350

Mr. Robert G. Byram Senior Vice President-Nuclear Pennsylvania Power & Light Company 2 North Ninth Street Allentown, Pennsylvania 18101

SUBJECT:

SUSQUEHANNA STEAM ELECTRIC PLANT MAINTENANCE RULE BASELINE

TEAM INSPECTION REPORT 50-387/98-04 & 50-388/98-04

Dear Mr. Byram:

This report transmits the findings of the safety inspection conducted by NRC inspectors at the Susquehanna Steam Electric Plant during the week of June 8, 1998. The purpose of this inspection was to review your implementation of the maintenance rule in accordance with 10 CFR 50.65. At the conclusion of this inspection, these findings were discussed with members of your staff.

Overall, we concluded that your facility had implemented the maintenance rule acceptably at the time of the inspection with the exception of the violation identified below. We are concerned, however, that before June 1998 significant performance weaknesses and inadequacies existed that indicated an apparent organizational ineffectiveness in initial implementation of the maintenance rule. We noted that a number of revisions and substantial improvements to your program were implemented just prior to this inspection.

Based on the results of this inspection, the NRC has determined that apparent violations of NRC requirements occurred. The violations were mostly self identified, but NRC identified a scoping violation. The self identified apparent violations included: 1) failure to include all required systems within the maintenance rule program, 2) failure to take into account all operating modes when evaluating risk significance, 3) failure to establish effective performance criteria, 4) failure to make timely performance reviews and properly classify functional failures, 5) failure to perform an adequate periodic assessment, and 6) failure to take timely actions to place systems in (a)(1) and make appropriate corrections.

We are continuing to review the violations as related to the past problem with maintenance rule implementation. We will contact you shortly on our enforcement action. In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room (PDR).

2

Your cooperation with us is appreciated.

Sincerely,
ORIGINAL SIGNED BY:

James T. Wiggins, Director Division of Reactor Safety

Docket Nos.: 50-387 & 50-388 License Nos.: NPF-14 & NPF-22

Enclosure: Inspection Report 50-387/98-04 & 50-388/98-04

cc w/encl:

R. F. Saunders, Vice President - Site Operations

G. T. Jones, Vice President - Engineering and Support

G. Kuczynski, General Manager - SSES

J. M. Kenny, Supervisor, Nuclear Licensing

G. D. Miller, General Manager - Nuclear Engineering

R. R. Wehry, Nuclear Licensing

F. P. Arcury, Nuclear Services Manager, General Electric

C. D. Lopes, Manager - Nuclear Security

A. Male, Manager, Nuclear Assessment Services

H. D. Woodeshick, Special Assistant to the President

J. C. Tilton, III, Allegheny Electric Cooperative, Inc.

R. A. Calvan, Regional Director, FEMA, Region III (EP Exercise/IRs Only) Commonwealth of Pennsylvania

Distribution w/encl:

Region I Docket Room (with concurrences)

Nuclear Safety Information Center (NSIC)

H. Miller, RA

W. Axelson, DRA

C. Anderson, DRP

P. Bonnett, DRP

R. Junod, DRP

NRC Resident Inspector

PUBLIC

DRS File Copy

Distribution w/encl: (Via E-Mail)

B. McCabe, OEDO

R. Capra, PD 1-2, NRR

V. Nerses, Project Manager, NRR

D. Brinkman, NRR

Inspection Program Branch, NRR (IPAS)

R. Correia, NRR

F. Talbot, NRR

M. Campion, ORA

DOCDESK

J. Lieberman, OE (2)

B. Fewell, RC

D. Holody, ORA

RI:DRS

RI:DRS RConte

7/\498

JW/iggins

RI:DRS

OFFICIAL RECORD COPY

g:\olhp\williams\sus9804.ins

LIST OF ACRONYMS USED

ADS Automatic Depressurization System

AOT Allowed Outage Time

ATWS Anticipated Transient Without Scram

BDID Back Draft Isolation Damper
CDF Core Damage Frequency
CM Corrective Maintenance

CR Condition Report
CRD Control Rod Drive

CREOASS Control Room Emergency Outside Air Supply System

CS Core Spray

EA Enforcement Action

EDG Emergency Diesel Generator
EOPs Emergency Operating Procedures
EPRI Electric Power Research Institute

ESW Emergency Service Water

FF Functional Failure

FSAR Final Safety Analysis Report

FW Feedwater

GDG General Design Guideline HCU Hydraulic Control Unit

HPCI High Pressure Coolant Injection

HVAC Heating, Ventilation, and Air-Conditioning

IFI Inspector Follow Item

IOE Industry Operating Experience IPE Individual Plant Examination

KV Kilovolt

LCO Limiting Condition of Operation

LLRT Local Leak Rate Test
MOV Motor Operated Valve

MPFF Maintenance Performance Functional Failure

MRC Maintenance Rule Coordinator
MRFF Maintenance Rule Functional Failure

MSIV Main Steam Isolation Valve

NUMARC Nuclear Utility Management and Resource Council

PM Preventative Maintenance

PORC Plant Operations Review Committee

PRA Probabilistic Risk Assessment
PSIG Pounds Per Square Inch Gage

QA Quality Assurance

RAW Risk Achievement Worth
RCIC Reactor Core Isolation Cooling

RCS Reactor Coolant System

RHR Residual Heat Removal System

RHRSW Residual Heat Removal Service Water

RMCS Reactor Manual Control System

RPS Reactor Protection System
RRW Risk Reduction Worth

SBO Station Blackout

SLCS	Standby Liquid Control System
SP	Support Procedure
SRV	Safety Relief Valve
SSCs	Structures, Systems and Components
SSES	Susquehanna Steam Electric Station
UCLF	Unplanned Capacity Loss Factor
UFSAR	Updated Final Safety Analysis Report
VAC	Volts Alternating Current
V DC	Volts Direct Current
WA	Work Authorization

LIST OF ITEMS OPENED AND/OR CLOSED

OPENED

EEI 50-378/388/98-04-01 Failure to place a safety related system within the maintenance rule program.

EEI 50-378/388/98-04-02 Failure to place systems in (a)(1) status in a timely manner.

EEI 50-387/388/98-04-03 Failure to perform an adequate periodic assessment.

EEI 50-387/388/98-04-04 Failure to implement an effective maintenance rule program.

IFI 50-387/388/98-04-05 Administrative controls of EOP and support procedures.

CLOSED

URI 50-387/388/97-03-04 Back draft isolation dampers tested and included in the maintenance rule program.

PARTIAL LIST OF PERSONS CONTACTED

Pennsylvania Power & Light Company Kevin Chambliss, Manager, Nuclear Operations Tom Fedorko, Operations Unit Supervisor Steve Geiger, Maintenance Rule Coordinator Cas Kukielka, PRA Engineer George Kuczynski, General Manager SSES Jerry Radishofski, Operations Supervisor Wilbur Slusser, Work Week Manager Jeff Sukal, Project Manager, Work Coordination Dave Walsh, Operations Shift Supervisor Bill Williams, Senior Licensing Engineer Robert Breslin, Manager, Nuclear Maintenance Dale Roth, Operations Engineering Supervisor G. Miller, General Manager, Nuclear Engineering Richard Pagodin, Manager, Nuclear Systems Engineering Mike Gorski, PP&L Inspection Team Lead Vince Kelly, Supervising Engineer Robert Prego, Supervisor, Surveillance Services

LIST OF INSPECTION PROCEDURES

IP 62706 Maintenance Rule